







X.590 Blade Assembly
S.3412 Feed Strip
S.6400 Points Base
S.6402 Rail Short Curve with Fishplate S.3006
S.6403 Rail Short with Rail Clip

plate S.3006
Rail Short with Rail Clip
L/H Curved Rail (Large Radius)
with Fishplate S.3006

S.6645 R/H Curved Rail (Large Radius) with Fishplate S.3006 S.6794 L/H Curved Rail (Large Radius) with Fishplate S.3566 S.6795 R/H Curved Rail (Large Radius) with Fishplate S.3566 ST.4048 Crank Lever Pivot Screw ST.4049 Crank Lever Pivot Nut ST.5097 Feed Strip Insulator ST.5158 Crank Lever R/H ST.5159 Crank Lever L/H ST.6030 Locking Spring

## For X.404 Point-Motor see Servicing Sheet No. 34

Modifications are made to Tri-ang Hornby models from time to time. If a spare part is required which does not coincide with the illustration, a full description should be given and, if necessary, a sketch or sample should accompany the order.

PRINTED IN ENGLAND

5.6644

SERVICING SHEET

1966

