


## MARK IV MOTOR

(For R.50, R.52, R.53, R.54, R.56, R.59, R.152, R.153)



### X.04

- X.04 Complete Motor
- X.62 Back Plate and Bearing
- X.67 Brush Arm and Brush
- X.68 Top Pole Piece with Diaphragm
- X.70 Front Plate and Bearing
- X.71 Armature and Commutator
- X.72 Worm and Thrust Bush
- X.73 Brush Spring and Insulator
- S.3030 Bottom Pole Piece
- S.5105 Magnet
- S.1011 Motor Securing Screw
- S.1019 Magnet Screw
- S.5097 Magnet Nut

