


MOTOR-X.500



X.500 Complete Motor X.567 Brush Arm and Brush X.571 Armature and Commutator


X.572 Front Plate and Armature Assembly including worm

X.654 Brush Spring and Insulator Two-start Worm S.2197

5.2206 Magnet and Motor Securing Screw S.3501 Top Pole Piece—Clear Hole

S.3502 Bottom Hole Piece-Tapped Hole

S.4200 Magnet 5.6484 Front Plate S.6485 Rear Bearing



POLES SHAFT DIA. ·0620" (1·575 m.m.) ARMATURE DIA. ... ·375" (9·53 m.m.) ... 0-1 AMP CURRENT ... TWO-START WORM DRIVE REDUCTION RATIO ... 13 to 1 ... ALCOMAX III MAGNET DELRIN BEARING ... ARMATURE SPEED 20,000 r.p.m.

Mudifications are made to Tri-ang Hornby models from time to time. If a spare part is required which does not coincide with the illustration, a full description should be given and, if necessary, a sketch or sample should accompany the order. We do not undertake to supply separate components for the parts listed with an X prefix, unless a separate 5 part number is shown.

PRINTED IN ENGLAND