


GRAVES, PANASONIC, PENZOIL, TOSHIBA

See overleaf for more single seaters



Motor Pinion
L.7085
fitted to all vehicles
from February 1982
Replaces
Motor Pinion
01796


List of Parts					
Ref. No.	Item	Ref. No.	Item	Ref. No.	Item
W.1439	Guide Blade Assembly	L.7085	Pinion	S.9746	Front Tyre
W.2051	Front Axle Assembly	M.2055	Motor with Pinion and Harness	S.9747	Rear Tyre
W.2052	Rear Axle Assembly	M.2985	Eyelet	S.9900	Front Hub
W.2189	Body Assembly,			S.9901	Rear Hub
	State colour marking				
L.5174	Body	S.2483	Axle	02545	Front Axle Spacer
L.5175	Underpan	S.9536	Contrate Gear	05192	Rear Axle Bearing
L.5176	Aerofoil	S.9706	Front Motor Bracket	05967	Drivers Head
		S.9707	Rear Motor Bracket	13402	Screw

HORNBY HOBBIES

Westwood, Margate,
Kent, CT9 4JX, England.

SERVICE SHEET No.157
Issued March 1992

TYLER, DUNLOP



Motor Pinion
L.7085
fitted to all vehicles
from February 1982
Replaces
Motor Pinion
01796

List of Parts					
Ref. No.	Item	Ref. No.	Item	Ref. No.	Item
W.1439	Guide Blade Assembly	L.7085	Pinion	S.9746	Front Tyre
W.2051	Front Axle Assembly	M.2055	Motor with Pinion and Harness	S.9747	Rear Tyre
W.2052	Rear Axle Assembly	M.2985	Eyelet	S.9900	Front Hub
W.2190	Body Assembly,			S.9901	Rear Hub
	State colour marking				
L.5183	Body	S.2483	Axle	02545	Front Axle Spacer
L.5184	Underpan	S.9536	Contrate Gear	05192	Rear Axle Bearing
L.5185	Aerofoil	S.9706	Front Motor Bracket	05967	Drivers Head
		S.9707	Rear Motor Bracket	13402	Screw